
54SX Family FPGAs RadTolerant and HiRel Errata

In Table 1 on page 8, the Maximum Input Tolerance for the A54SX16 and A54SX32 devices is incorrect.

Here is how the table should appear.

Table 1 • Supply Voltages

Devices	V _{CCA}	V _{CCI}	V _{CCR}	Maximum Input Tolerance	Maximum Output Drive
A54SX16 A54SX32	3.3V	3.3V	5.0V	5.0V	3.3V
RT54SX16 RT54SX32	3.3V	3.3V	5.0V	5.0V	3.3V

Actel and the Actel logo are registered trademarks of Actel Corporation.
All other trademarks are the property of their owners.



<http://www.actel.com>

Actel Europe Ltd.

Maxfli Court, Riverside Way
Camberley, Surrey GU15 3YL
United Kingdom

Tel: +44 (0)1276 401450

Fax: +44 (0)1276 401590

Actel Corporation

955 East Arques Avenue
Sunnyvale, California 94086
USA

Tel: (408) 739-1010

Fax: (408) 739-1540

Actel Asia-Pacific

EXOS Ebisu Bldg. 4F
1-24-14 Ebisu Shibuya-ku
Tokyo 150 Japan

Tel: +81-(0)3-3445-7671

Fax: +81-(0)3-3445-7668